

STRICTLY
TESTED



PROUDLY
AUSTRALIAN OWNED



QuietFlow 2 Inlet
Valve Repair Kit
Replacement seals for Caroma
QuietFlow 2 Inlet Valve

CAROMA
Genuine Parts

CAROMA
Genuine Parts



ENGINEERED FOR AUSTRALIAN
& NEW ZEALAND CONDITIONS



EASY TO
INSTALL



GWA
Bathrooms & Kitchens

CAROMA INDUSTRIES LIMITED
1 Melito Court, Prestons NSW 2170
ABN 35 000 189 499

Caroma Customer Care ☎ 13 14 16



caroma

Scan for
installation
instructions or
see overleaf



Product Code: 405888





9 3 1 1 4 4 0 4 9 5 9 5 2

caroma.com.au
Made in China


QuietFlow 2 Inlet Valve Repair Kit

Service/Repair Instructions


1. Turn off water, flush cistern and remove cistern lid.
2. Rotate Cap Assembly clockwise (1) & pull to remove (2).
3. Replace Seal onto Cap Assembly.



4. Push (1) & rotate anti-clockwise (2) to re-attach cap assembly.



Tip: For continued performance, remove and wash tail strainer and carefully replace back into valve tail.



Always ensure work is carried out by a licensed plumber. Warranty claims can only be made with proof of installation by a licensed plumber. For complete warranty details, please visit our website:
www.caroma.com.au