




ASSEMBLE PARTS AS SHOWN


LOCATE URINAL WASTE

INSERT ASSEMBLY AS SHOWN









ROTATE ASSEMBLY 90 DEGREES AND ENSURE HOOK ENGAGES INTO WASTE

TIGHTEN SCREW A, ENSURING HOOK AND BRIDGE FIRMLY ENGAGE ONTO URINAL. REMOVE SCREW B.

LOCATE GRATE CORRECTLY ONTO BRIDGE. INSERT SCREW B INTO GRATE AND TIGHTEN ONTO ASSEMBLY

CHECK AND ENSURE THAT GRATE IS FIRMLY ATTACHED TO URINAL